

FIG. 1




FIG. 2-




FIG. 3a





FIG. 3b

	Fanin signatures		Fanout s	signatures
	ABE	DJ	С	BF
	<i>S9</i>	S11	S9	S11
	I45	I59	I45	I59
		S7	S57	S29
		I35	I14	I8
			S80	S64
			I26	I53
			I75	
			I76	
	Fanin signatures		Fanout s	signatures
	ABE	DJ	С	BF
	<i>S9</i>	S11	S9	S11
	I45	I59	I45	159
			S57	S29
			I14	I8
			S80	S64
			I26	I53
-			I75	
			I76	

FIG. 4



-250	In[1]	In[2]	In[3]	Out[1]	Out[2]	Out[3]
\	0	0	0	0	1	0
	0	0	1	1	1	1
	0	1	0	0	1	1
Don't care input	0	1	1	1	0	1
Don't care input	1	0	0	0	0	0
Don't care input	1	0	1	1	0	1
DON COMP IN-	1	1	0	1	1	0
	1	1	1	0	1	0
1						
255	In[4]	In[5]	In[6]	Out[4]	Out[5]	Out[6]
*	0	0	0	0	11_	0
	0	0	1	1	1	1
	0	1	0	0	1	1
Don't care input	0	1	1	0	11	1
	1	0	0	0	0	0
Don't care input	1	0	1	0	0	1
	1	1	0	1	1	$\frac{1}{0}$
	1	1	1	0	1	0

FIG. 5




FIG. 6




FIG. 7




FIG. 8